

**To:** Weigel, Greg[Weigel.Greg@epa.gov]  
**Cc:** R8\_Documentation\_Unit\_Leader@epa.gov[R8\_Documentation\_Unit\_Leader@epa.gov]  
**From:** Lloyd, Lisa  
**Sent:** Thur 8/20/2015 8:49:21 PM  
**Subject:** FW: Sit Update  
P1030136.jpg  
P1030137.jpg  
P1030138.jpg

*Lisa Lloyd*

*Situation Unit Leader*

*U.S. EPA Region 8*

*(303) 312-6537*

**Personal Phone/Ex. 6**

**From:** Lloyd, Lisa  
**Sent:** Thursday, August 20, 2015 1:12 PM  
**To:** Personal Email/Ex. 6  
'butch.knowlton@com.aprata.co.us'; 'david.osborn@state.co.us'; 'rew.petersen@state.co.us'; 'Hoecker, Terry'; 'karen.takai@state.nm.us'; Kathi Gurule; 'ljollon@sjbhd.org'; 'msouder@southernute-nsn.gov'; Myers, Craig; 'oem@sanjuancountycolorado.us'; 'sclow@utemountain.org'; 'thomas.mcnamara@co.laplata.co.us'  
**Cc:** Karen Dickson; Deirdre Rothery; Brobst, Bob  
**Subject:** FW: Sit Update

FYI – if you get calls about the water

*Lisa Lloyd*

*Situation Unit Leader*

*U.S. EPA Region 8*

*(303) 312-6537*

**Personal Phone/Ex. 6**

**From:** Carreon, Michel A MST1 [mailto:[Michel.A.Carreon@uscg.mil](mailto:Michel.A.Carreon@uscg.mil)]  
**Sent:** Thursday, August 20, 2015 12:58 PM  
**To:** Jolly, Danica A MSTC; Lloyd, Lisa  
**Subject:** Sit Update

Greetings,

San Juan County has resumed road construction near the Gold King Mine operation. The photos show an increased sediment load in Cement Creek due to these activities.

Very Respectfully,  
-M. Carreon, MST1

USCG Atlantic Strike Team  
5614 Doughboy Loop  
Fort Dix, NJ 08640  
PH: (609) 724-0008  
FX: (609) 724-0232  
Cell: Personal Phone/Ex. 6